



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

ODI RESUME

Investigation: PE 05-031
Date Opened: 06/15/2005
Principal Investigator: *Bob Young*
Subject: Fuel Leak

Manufacturer: American Suzuki Motor Corp.
Products: MY 2000-02 Suzuki Intruder 1500 Motorcycles
Population: 10,000 (ESTIMATED)

Problem Description: Leak from fuel tank.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	8	0	8
Crashes/Fires:	0	0	0
Injury Incidents:	0	0	0
# Injuries:	0	0	0
Fatality Incidents:	0	0	0
# Fatalities:	0	0	0
Other*:	0	0	0

*Description Of Other:

Action: Open this PE

Engineer: *Bob Young*
Div. Chief: *Richard Boyd*
Office Dir.: *Kathleen C. DeMeter*

Date: 06/15/2005
Date: 06/15/2005
Date: 06/15/2005

Summary: Eight subject motorcycle owners allege fuel leaks from hairline cracks at the fuel tank/mounting tab interface.